Grip-It T

Heavy Duty Anti-Slip Treatment for Ceramic & Porcelain Tiles

+ Common problems, likely causes & solutions
+ Read the label, SDS & Technical Bulletin before use
+ Always test a small, hidden area first
+ Still stuck? Our Technical Support team can help

Product page, TB, SDS & more

How to use this guide: find your problem in the first column, check the likely cause, then follow the solution. The solutions are the most direct fix, not the only one. If your problem isn't listed, or the solution doesn't fix it, it's most likely job specific: contact Sealers Plus Technical Support (support@sealersplus.com.au · 02 9521 4000, Mon – Fri 9.00am – 4.00pm). **Always read the entire label, SDS & Technical Bulletin before use and do a test area first.**

PROBLEM	LIKELY CAUSE	SOLUTION
Tile surface still feels slippery after treatment.	• **Grip-It T** not left to dwell long enough to create a suitable micro-texture.	• Repeat the process, or allow a longer dwell time, until the desired micro-texture is achieved.
Gloss or polished tile looks dull after treatment.	• **Grip-It T** creates a micro-texture on the tile surface to help improve slip resistance. The more slip resistance is increased, the more the gloss or polish is reduced.	• No action needed.
Treated tile has lost some colour.	• The micro-texture that helps improve slip resistance also reduces the colour of the glaze, especially on dark tiles.	• Seal with **Enhance'N'Seal** to enhance the colour of the treated tile and make future maintenance easier.
Treated surface shows spots, streak marks or an uneven look.	• Tiles not cleaned and prepared properly before applying **Grip-It T**. • Application tools contaminated or not clean. • **Grip-It T** dripped onto the surface during application. • Uneven application. • **Grip-It T** allowed to dry on the surface. • Not neutralised or rinsed thoroughly.	• Repeating the process may even out the overall look. • Damaged tiles may need to be replaced.
Treated surface is harder to clean, shows marks (foot or hand prints) and/or residue is visible.	• The micro-texture can attract dirt and grime. • Cleaners used on the treated floor have not been rinsed thoroughly.	• Seal with **Aqua-Seal Gold+** to seal the porous surface and make future maintenance easier. • Use **EzyClean+** and a microfibre mop for regular cleaning, and **XtremeClean+** for periodic heavy-duty cleaning.
Etched or tarnished metal.	• Acids will etch or tarnish most metal surfaces.	• Protect acid-sensitive surfaces. • Do not expose metals to acid: the damage can't easily be repaired.
Grout colour has bleached.	• Acid will bleach the pigments in grout. • Grout not pre-wet first. • Acid solution too strong. • Acid residue not neutralised or rinsed thoroughly.	• Always pre-wet the surface and grout joints with clean water first. • Neutralise after use with several rinses of clean water. • Repair bleached or damaged grout colour with **Colour'N'Seal** Premium Grout Colourant.
Grout is powdery, or sand is coming out of the joint after the acid wash.	• Acid has damaged the cement binder in the grout. • Grout not pre-wet first. • Acid solution too strong. • Acid residue not neutralised.	• Use as weak an acid solution as possible to complete the task. • Always pre-wet the surface and grout joints with clean water first. • Neutralise after use with several rinses of clean water.

RELATED PRODUCTS – TAP TO VIEW: **Enhance'N'Seal** · **Aqua-Seal Gold+** · **EzyClean+** · **XtremeClean+** · **Colour'N'Seal**

GRIP-IT T DOCUMENTS: Technical Bulletin › · SDS › · Product page ›

STILL STUCK? Email photos of the problem, the surface type and the product batch number to support@sealersplus.com.au or call 02 9521 4000.

Watch: Anti-Slip Tile Treatment: Grip-It T for Tiles
Watch how to use it on our YouTube channel
youtu.be/FwfDy1KAxNA

MADE IN AUSTRALIA · Sealers Plus (An Aqua-Seal Brand).

PRODUCT WARRANTY – SEALERS PLUS (A Division of Aqua-Seal STS™) "The Manufacturer" warrants to the original purchaser of its products that such products are free from manufacturing defect and does not warrant or guarantee the workmanship performed by any person or firm installing its products. The manufacturer's obligation under this warranty is limited solely to the original purchaser and solely shall be limited to the replacement of the product sold or refund. This warranty will not extend to any product which has been modified in any way or which has not been used in accordance with the printed instructions. The manufacturer makes no other warranties either expressed or implied. The end user must determine the suitability of the product for their intended use. ALWAYS READ ENTIRE LABEL, SDS & TECHNICAL BULLETIN BEFORE USE & TEST FIRST.

SEALERS PLUS (An Aqua-Seal Brand) – Technical Support
P: +61 2 9521 4000 Monday to Friday 9.00am – 4.00pm E: support@sealersplus.com.au
U5, 5 Clerke Place, Kurnell NSW 2231 Australia
Aust: sealersplus.com.au **NZ:** sealersplus.co.nz **Global:** sealersplus.com

© October 2026